Notice



☐ CORRECTION ● PRODUC ☐ SERVICE FLASH ☐ ADD INFO	TION CHANGE DRMATION FILE NO.						
Please add this notice to the Service Manual listed below. REVISION 0							
Category: COLOR TELEVISION	Date: MARCH / 23 / 2011						
Model: DP42740	Effective from : Chassis No. P42740-02	<u> </u>					

NOTE: Match the Chassis No. on the unit's back cover with the Chassis No. in the Service Manual. If the Service Manual Chassis No. does not match the unit's, additional Service Literature is required. This chassis is similar to Chassis No. P42740-00. Only the difference Service Information is given in this manual. For detailed Service Information, refer to the Original Service Manual and Notices for Chassis No. P42740-00 used in Model DP42740 (SM780173).

REF : **No. SM780173-02**

SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

1. IN THE SERVICE ADJUSTMENTS

Destination: U.S.A. / CANADA

PAGE 4 ON-SCREEN SERVICE MENU

Item No. 088 OP2 Data should be 1Ah in the table and in Note 2.

2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

The reason for change.

A: Misprint B: Quality Reliability C: Standardization

D: Design E: Add as a possible sub F: Schematic location change

G: Purchasing Request

	Page & Section	Schematic Location		Part No.	Description	Q'ty	Interchange- ability	Reason
	Page 21, Chassis Electrical Parts List	Old	1AV4T44B03000	PDP MODULE	1	ОИ	D	
-		New	1AV4T44B03100	PDP MODULE	1	NO	D	

For parts or service contact:
Sanyo Manufacturing Corporation
P.O. Box 2000
3333 Sanyo Road
Forrest City, Arkansas 72335-2000

March 2011 SMC Published in Mexico

© Sanyo Manufacturing Corporation 2011